



## GAS TUNGSTEN ARC WELDING (TIG) TROUBLESHOOTING TIPS

**1-800-272-7637**

PROBLEM	POSSIBLE CAUSE	POSSIBLE SOLUTION
Excessive electrode consumption	<ul style="list-style-type: none"> <li>Inadequate gas flow</li> <li>Operating on DCEP</li> <li>Improper electrode size or tip too sharp for required current</li> <li>Excessive heating in holder</li> <li>Contaminated electrode</li> <li>Electrode oxidation during cooling</li> <li>Using gas containing oxygen or carbon dioxide</li> </ul>	<ul style="list-style-type: none"> <li>Increase gas flow</li> <li>Use larger electrode or change to DCEN</li> <li>Use larger electrode or correct tip shape</li> <li>Check concentricity and contact with collet and tighten if necessary</li> <li>Remove contaminated portion</li> <li>Keep inert gas flowing for 15 seconds after extinguishing arc</li> <li>Change to proper gas for the application</li> </ul>
Erratic arc	<ul style="list-style-type: none"> <li>Base metal dirty or greasy</li> <li>Joint is too narrow</li> <li>Contaminated electrode</li> <li>Arc is too long</li> <li>Magnetic fields affecting the arc</li> <li>Incorrect electrode size</li> <li>Gas flow problems</li> <li>Tungsten tip irregular, bad finish, or nonaxial ground</li> </ul>	<ul style="list-style-type: none"> <li>Use appropriate cleaners, wire brush, or abrasives</li> <li>Open joint groove; bring electrode closer to work: decrease voltage</li> <li>Remove contaminated portion</li> <li>Shorten arc</li> <li>Rearrange workpiece connection; use magnetic arc stabilizer; degauss metal and tooling</li> <li>Use electrode with minimal diameter that will handle maximum current</li> <li>Check flow control and sufficiency of gas supply</li> <li>Prepare tip properly; consistent finish and angle</li> </ul>
Porosity	<ul style="list-style-type: none"> <li>Entrapped gas</li> <li>Defective gas hose or loose connection</li> <li>Oil film on base metal</li> <li>Contaminated filler metal</li> <li>Base metal has high gas content or impurities</li> <li>Dye penetrant media not completely removed</li> </ul>	<ul style="list-style-type: none"> <li>Purge air from lines before striking arc: remove condensed moisture from lines and work; use welding-grade inert gas</li> <li>Check hose and connections for leaks: do not use rubber hoses; viton or polyethylene hoses are acceptable; replace contaminated hoses</li> <li>Clean with approved chemical cleaner. Do not weld while base metal is damp</li> <li>Clean filler metal or use fresh supply</li> <li>Use different base; use low-penetration passes</li> <li>Grind base metal until all traces of penetrant are removed</li> </ul>
Cracking	<ul style="list-style-type: none"> <li>Geometric restraint</li> <li>Thermal stresses</li> <li>Insufficient root thickness</li> <li>Hot cracking</li> <li>Metallurgical imbalances</li> <li>Filler metal problems</li> </ul>	<ul style="list-style-type: none"> <li>Use joint designs that avoid excessive restraint</li> <li>Use more passes to reduce heat input</li> <li>Reduce travel speed or increase current</li> <li>Use correct travel speed and current to reduce melting.</li> <li>Use filler metal that is free of low melting constituents</li> <li>Make sure filler metal is correct for base metal</li> <li>Add filler metal at correct rate for current and travel speed</li> </ul>
Tungsten contaminates weld metal	<ul style="list-style-type: none"> <li>Contact starting with tungsten electrode</li> <li>Electrode melting and alloying with base metal</li> <li>Touching electrode to molten pool</li> <li>Welding current too high or erratic</li> </ul>	<ul style="list-style-type: none"> <li>Use high frequency or other starter; use copper striking plate</li> <li>Use less current (especially during starting) or larger electrode</li> <li>Use longer arc length</li> <li>Reduce arc current or increase electrode size</li> </ul>

Excerpted from C5.5/C5.5M:2003, *Recommended Practices for Gas Tungsten Arc Welding*, June 2007