


CRYOTHERM® TORCH KIT

Low temperature metallizing

For all metals (except pure copper).

BEFORE AND AFTER:

In just a few minutes this worn shaft was restored. Photo shows the shaft in its worn condition... and after metalizing with the **CRYOTHERM** low temperature process.



6

Everything you need is packaged in one case.

CRYOTHERM torch
CRYOTHERM bonding powder

CRYOTHERM final coat powder
CRYOTHERM cleaning solvent
Carbide cutting tool

The **CRYOTHERM** torch is simply attached to your oxygen and acetylene hose. **CRYOTHERM** metal powder modules screw onto the torch. A thumb actuated on-off valve lets the metal powder feed into the flame through a preset orifice, assuring controlled flow. No adjustment is required.



(See page 96)